

Charging Port Cap Installation

Tools and Parts

| Part Name | LDAR Part # |
|--------------------------------------|-------------|
| 6/32 x 3/8 low head socket cap screw | 42060 |
| 1/16" Hex bit | 4226 |
| Charging port cap | 42013 |

Procedures

1. **Charging Port Cap** screw removal:
 - a. Using the **1/16" hex bit**, remove the **6/32 x 3/8 low head socket cap screw** by turning counterclockwise.
2. **Charging Port Cap** installation:
 - a. Take the **6/32 x 3/8 low head socket cap screw** and place it through the mounting hole of the tether that is connected to the **charging port cap**.
 - b. Thread the **6/32 x 3/8 low head socket cap screw** now attached to the **charging port cap** into the face of the **phx42**.
 - c. Orient the tether so that it points to the left when viewing the front faceplate of the **phx42**.
 - d. Tighten the **6/32 x 3/8 low head socket cap screw** until snug. (Be careful to not overtighten and strip the head of the screw).