



### H<sub>2</sub> Fill Port Variations

Below are the two versions of the phx42 H<sub>2</sub> Fill Port (LDAR# 42801). It is important to recognize the distinctions between each type and which one applies to your unit.



1

Original H<sub>2</sub> Fill Port. Follow best practices when filling to prevent contamination. If a replacement is needed during an RMA, v2 will be provided.



2

v2 H<sub>2</sub> Fill Port with the filter in place. No action required.



3

v2 H<sub>2</sub> Fill Port *missing the filter*. Report an issue.

If your phx42 contains the v2 H<sub>2</sub> Fill Port, but is missing the filter (as shown above in figure 3), please report an issue immediately.